## FORKLIFT PALLET TRUCK HEIGHT INDICATOR



## **Pallet Height Indicator**

- 1. Mount system to the forklift mast
- 2. The bottom of the indicator should be positioned at 24".
- 3. Adjust cushioned pipe clamp as required
- 4. Position two magnet mounting to keep plastic tube stable
- 5. System can be mounted on the mast to the left or right side of the mast.

PHI-96-I (inches) PHI-96-M (cm)



www.skidweigh.com



## Lift Truck Pallet Height Measurement Kit For Applications With CubeFreight Systems

